NORTH 1/4 COR. NORTHEAST SEC. COR SECTION 3 SECTION 3 1/16TH COR. BELMONT DRIVE FD. BRASS DISC FALLS 0.17 WEST FD. BRASS DISC FD. BRASS DISC N 89° 05' 26" W 1325.97 392.70 399.96 522.42 1325.97 10.89 DEED GAP 50 50 BK M. PG 149 23. BK J. PG 380 BK L. PG 578 PARCEL I FEE NO. 891471 544 <u>.</u> 87 N 89°05'26"W 399.96 399.30 \$ 89°05'26"E 803.55" PER DEED BK M. PG 88 326 326 BK L. PG 3 PARCEL 2 FEE NO. 891471 392.70 399.30 N 89°05'26"W 726.55 77.00 BK 7. PG 337 PARCEL 3 FEE NO. 891471 BK L. PG 579 2612. $\overline{\circ}$ 260 2593.54 726.55 725.94 Ω N 89° 05' 26" W 0.61 N 89°05'26"W 23. 29 FEE NO. 732519 0 BK L. PG 508 PARCEL 4. FEE NO. 891471 BK L. PG 404 20. 725.98 596.93 ORIGIN UNKNOWN FALLS 1.33 NORTH 1.22 WEST S 89°23.44°E S 1/2. SW 1/4. NE 1/4 BK K. PG 13 650 1321.90 CENTER 1/4 COR. S 89°29'52"E 1321.90 1/16TH COR. SECTION 3 CALCULATED FD 1/2° IRON ROD PER C.S.* 0658 NOT LEGAL CENTER OF SECTION ACCEPTED FOR THIS SURVEY

SURVEY

NORTHEAST 1/4 SECTION 3 T2 NORTH RIO EAST. W.M. HOOD RIVER COUNTY, OREGON

FOR: FRANK ERICKSON

O SET 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED "WYEAST SURVEYS PLS 2393"

The purpose of this survey is to monument the boundaries of those tracts of land described in deed per Fee No's 732519 and 891471 Hood River County Deed Records.

The West half of the Northeast Quarter of Section 3 was partitioned into parcels and sold by Miles Potter between 1903 and 1908. The deeds of record reflecting these partitions are shown on the accompanying map. The legal descriptions contained in the deeds leave numerous gaps between the parcels. The use of different points of beginning in the deeds appears to be the main reason for the discrepancies. It is obvious that the common grantor did not intend to leave these gaps in the parcels he sold. Therefore in the resolution of the boundaries gaps were eliminated through use of surveying principles, reasoned analysis and common sense. It is recognized that another surveyor also using reasoned analysis might come up with another solution. Where no clear resolution was arrived at the discrepancy is shown as a deed gap.

Deed calls were held whenever possible. Senior rights were not interfered with.

The iron rod found at the Center of Section was held over the "legal center" as it tended to close the gap significantly between certain parcels.

When the parcel described by Bk 7 Pg 337 was taken out of the larger parcel described in Bk L Pg 579 in 1912 it was not sold to any of the owners of adjacent parcels. Therefore, it is believed that the West lines of Bk 7 Pg 337 and Bk L Pg 508 were not intended to be continuous. By holding deed calls a jog of 0.61 feet separates the two.

The Northwest corner of Bk L Pg 508 was established S 89° 29' 52" E. 726 feet and N 01° 23' 55" E. 1320 feet from the Center Quarter corner per deed.

The Southwest corner of Bk L Pg 578 was established as coincident with the Northwest corner of Bk L Pg 3 rather than by holding deed calls.

REGISTERED PROFESSIONAL LAND SURVEYOR

Kern Dow OREGON KEVIN DOWD 2393 MAY 20, 1994

JUN 1 5, 1994 Kill a And

WYEAST SURVEYS KEVIN DOWD 4399 WOODWORTH DR. MT. HOOD, OR 97041 (503) 352-6065

EAST 1/4 COR. SECTION 3 FD. 2 1/2° IRON PIPE

SCALE I - 200 FEET