

SCALE IN FEET

0' 1 2 3 4 5'

NOTES:

BEARINGS BASED ON WEST LINE OF THE N.W. 1/4, SECTION 34, TWP. 3 N., RANGE 10 E. W.M. WATER SUPPLIED BY WESTSIDE WATER DISTRICT.

SUBSURFACE SEWAGE DISPOSAL EVALUATIONS HAVE BEEN COMPLETED ON PARCELS 1 AND 3 AND FOUND SUITABLE. PARCEL 2 IS AN EXISTING DRAINFIELD IN SUITABLE WORKING CONDITION. COPIES OF REPORTS ARE ON FILE WITH THE HOOD RIVER COUNTY SANITARIANS OFFICE.

PARTITION PLAT

TAX LOT 1506, MAP 3N-10-34B IN THE W.1/2 OF N.W.1/4, SECTION 34, TOWNSHIP 3 NORTH, RANGE 10 EAST, W.M. HOOD RIVER COUNTY, OREGON MARCH 18, 2003

RECORDING INFORMATION

at 3:52 P.M.


Plat Number 200307-P instrument received on the 25th day of MARCH

Hood River County Director of Records and Assessments.

OWNER:

MICHAEL J. SPEDICK AND PEGGY J. SPEDICK, H. & W. 3509 CONRAD DRIVE. BEND, OREGON. 97701 PH. (541) 617-0075

ZONING R-1



NOTES:

RELATIVE ACCURACY: THIS SURVEY WAS CLOSED TRAVERSE WITH A MAXIMUM RELATIVE ERROR OF 1 PART IN 10,000.

EQUIPMENT:

WILD T-1600, 0°00'01" THEODOLITE AND WILD DI-2000 ELECTRONIC DISTANCE MEASURING UNIT.

CLOSED FIELD TRAVERSE USING DOUBLED ANGLE MEASUREMENT AND AVERAGE OF DISTANCE READING.

PARCEL 1 219,965 S.F. = 5.05 AC. PARCEL 2 219,400 S.F. = 5.03 AC. PARCEL 3 218,583 S.F. = 5.02 AC.

657,948 Sq.Ft.=15.10 Acres TOTAL (TAX LOT 1506, 3N-10-34B)

DETAIL "A" SCALE: 1"= 5"

1/16 LINE

N.89°02'40"W

SURVEYOR'S CERTIFICATE:

X 30" REBAR WITH YELLOW PLASTIC CAP #385, AS SHOWN.

NARRATIVE:

I, DONALD J. BRANTON, REGISTERED LAND SURVEYOR #385 IN THE STATE OF OREGON, BEING FIRST DULY SWORN, DEPOSE AND SAY THAT I HAVE CORRECTLY EXECUTED, ACCORDING TO HOOD RIVER COUNTY LAND USE ORDINANCE AND ORS CHAPTER 92, A PARTITION PLAT LYING IN PARCELS 1 AND 2 OF PARTITION PLAT 94-04, AS ADJUSTED IN PLA 99-48, IN THE WEST 1/2 OF THE NORTHWEST 1/4 OF SECTION 34, TOWNSHIP 3 NORTH, RANGE 10 EAST, WILLAMETTE MERIDIAN, HOOD RIVER COUNTY, OREGON. THE INITIAL POINT FOR SAID PLAT IS THE NORTHWEST CORNER OF THE SUBJECT TRACT, SAID INITIAL POINT IS A 5/8" X 30" REBAR WITH YELLOW PLASTIC CAP INSCRIBED "BRANTON LS 385" SET IN THE WEST LINE OF SAID NORTHWEST 1/4, SAID INITIAL POINT BEARS SOUTH 00°34'52" WEST 1,256.26 FEET FROM A U.S. ARMY CORPS OF ENGINEERS BRASS CAP MONUMENT SET AT THE NORTHWEST CORNER OF SAID SECTION 34. THE PLATTED PROPERTY IS DESCRIBED AS FOLLOWS.

THE PURPOSE OF THIS SURVEY WAS TO DIVIDE PARCEL 2 OF ORIGINAL PARTITION PLAT 94-04 AND PLA 99-48 CONSISTING OF 15.03 ACRES INTO THREE 5 ACRE + TRACTS. THE WEST 1/4

CORNER AND NORTHWEST CORNER OF SECTION 34 WERE RECOVERED AS PER PRIOR SURVEY

PARTITION PLAT 94-04, PROPERTY LINE ADJUSTMENT 99-48. THE NORTH LINE PROPERTY LINE ADJUSTMENT PINS WERE FOUND WITHIN ACCEPTABLE TOLERANCES, SURVEYOR #932. ALSO FOUND

OWNERSHIP. HOOD RIVER COUNTY PLANNING AND DEVELOPMENT OFFICE CONCURRED WITH THE

USE OF FENCE LINE RATHER THAN THE PLA PLATTED LINE CALLS. SET ALL CORNER PINS, 5/8"

RECORDS. THE DIMENSIONS CALLED OUT WERE USED AS THE BASIS FOR LAYOUT AS PER

WAS AN EXISTING FENCE LINE ADJACENT TO THE NORTH BOUNDARY LINE OF THE PLA

ADJUSTMENT PLAT WHICH INCLUDES A SMALL PORTION OF TAX LOT 1505 WITH THE SAME

BEGINNING AT THE AFORESAID INITIAL POINT; THENCE CONTINUING SOUTHERLY ON SAID WESTERLY LINE, SOUTH 00°34'52" WEST 63.20 FEET; THENCE LEAVING THE WEST LINE OF SAID SECTION 34, SOUTH 89'02'40" EAST 1.32 FEET; THENCE SOUTHERLY, PARALLEL WITH THE WEST LINE OF SAID SECTION 34, SOUTH 00°34'52" WEST 659.64 FEET; THENCE SOUTH 88°54'13" EAST 34.74 FEET; THENCE SOUTH 00°50'48" WEST 40.67 FEET; THENCE SOUTH 88°57'56" EAST 829.39 FEET TO THE SOUTHEAST CORNER OF SAID ADJUSTED PARCEL 2; THENCE NORTHERLY ALONG THE EAST LINE OF SAID ADJUSTED PARCEL 2. NORTH 00°32'55" EAST 758.48 FEET; THENCE NORTH 87°42'28" WEST 106.03 FEET TO THE COMMON LINE BETWEEN SAID ADJUSTED PARCELS 1 AND 2; THENCE CONTINUING NORTH 87'42'28" WEST 181.10 FEET; THENCE NORTH 89'05'16" WEST 577.81 TO SAID POINT OF BEGINNING.

CONTAINS 15.10 ACRES.

SUBJECT TO ALL EASEMENTS, AGREEMENTS, AND RIGHTS-OF-WAY OF RECORD.

MAR 2 7 2003

ENGINEER / SURVEYOR:

TENNESON ENGINEERING CORP. 409 Lincoln Street, The Dalles, Oregon. 97058 Ph. 541-296-9177

FAX 541-296-6657

OREGON OCTOBER 13, 1956 DONALD J. BRANTON

EXPIRES: 12/31/03 SHEET 2 OF

REGISTERED

PROFESSIONAL

LAND SURVEYOR

FND. REBAR, PLS. 932 (REF. #1) PARCEL 1, P.L.A. 99-48 N 89°07'54" W N.16*14'28"E - 0.42' PARCEL 2, P.L.A. 99-48 N 87°42'28" W -X----X-----X FND, REBAR, PLS. 932 S.87°12'28"E-0.14" FROM PART, PLAT LINE ALONG N.E. COR. PARCEL 3. EXISTING FENCE LINE FIRE DEPARTMENT TURNAROUND EASEMENT. N 89*02'40" W 1/16 LINE FND. REBAR, PLS. 932 S.01°06'16"W-0.59'

DETAIL "B"

SCALE: 1"= 5'

MAR 2 5 2003

Certified to be a true and correct copy of the ORIGINAL Deprot Recoxis 8y Assessment by Charles Deputy

I HEREBY CERTIFY THAT THIS PLAT IS A TRUE AND EXACT COPYS OF THE ORIGINAL PLAT. genele 3-18-13 DONALD J. BRANTON DATE