W 1/16 CORNER CALCULATED POSITION BASED ON CS-80082 FOUND 2-1/2" PIPE WITH 2-1/2" BRASS CAP PUSHED OVER. FOUND 6" NAIL NEXT TO PIPE I COULD NOT HOLD THIS -1/4 CORNER PIPE BECAUSE IT WAS CALCULATED POSITION DISTURBED BASED ON CS-80082 (S 88'35'33" W - 1280.18' CS-2006 064) WITH 3" BRASS CAP OREGON STATE BOARD (\$ 88'35'33" W - 1280.18' CS-80082) (S 88'35'33" W - 1297.71' SN-80082) OF FORESTRY N 88'35'30" E - 1280.26' N 88'35'30" E - 1297.79' DATED 1972 TAX LOT 300 CN NW 1/64 CORNER CALCULATED POSITION NN 1/64 CORNER—
CALCULATED POSITION
BASED ON CS-80082
FOUND 5/8 " REBAR WITH
YELLOW PLASTIC CAP
N 79'19'12" E AT 0.48' BASED ON CS-80082 (N 88°36'42" E - 1273.87' CS-2006 064) FOUND 5/8 " REBAR WITH N 88°36'40" E - 1273.94' YELLOW PLASTIC CAP N 42'14'23" E AT 1.54' N TAX LOT 400 SEE CS-2008 064 LONGVIEW TIMBERLANDS, LLC PROPERTY CORNER
SET 5/8" REBAR WITH
1-1/2" ALUMINUM CAP SEE CS-2006 064 INST. NO. 2007-0260 CN 1/16 CORNER CALCULATED POSITION month coincil cinia lama buena disiar cubia condi cunad incisio lama basia CALCULATED POSITION
BASED ON CS-80082
FOUND 2-1/2" PIPE WITH
2-1/2" BRASS CAP
N 22'36'27" E AT 6.62'
SEE CS-80082 NEW REFERENCES: N 88'37'15" E - 1270.79' 13" FIR S76"W AT 15.55" STEEL FENCE POST NEW REFERENCES: NORTH AT 1.0' 5" FIR N58'E AT 1.65" M TAX LOT 500 STEEL FENCE POST SOUTH AT 1.0' N 88'37'51" E - 1267.63' N 89°26'03" E - 1279.87' (\$ 88°37'52" W - 1267.56' SN-80082) N 1/16 CORNER (S 88'37'52" W - 1279.79' SN-80082) CALCULATED POSITION BASED ON CS-80082 NW 1/16 CORNER—
CALCULATED POSITION
BASED ON CS-80082 FOUND 2-1/2" PIPE WITH 2-1/2" BRASS CAP N 18'50'04" E AT 6.34' SEE CS-80082 100 N 88°40'13" E - 1255.01' N 88°40'13" E - 1261.95' (N 88'40'15" E - 2516.81' SN-80082) LEGEND SECTION CORNER, 1/4 CORNER AS NOTED FOUND MONUMENT AS NOTED SET 5/8" X 30" REBAR WITH 1-1/2" ALUMINUM CAP STAMPED "PROP COR 2210" CALCULATED POSITION WITH 3" BRASS CAP OREGON STATE BOARD OF FORESTRY RECORD BEARING AND/OR DISTANCE AS NOTED DATED 1972 LINE MARKED WITH 1/2" X 60" FIBER GLASS RODS RED AND WHITE RIBBON ON LINE BEWTEEN RODS TREES ALONG LINE PAINTED WITH BLUE PAINT

HOOD RIVER COUNTY SURVEYOR'S OFFICE

SURVEY NO.CS.2007124


FILED DATE: 12/10/07

BY: Roll 12/15/07

RECORD OF SURVEY
FOR
LONGVIEW TIMBERLANDS, LLC
IN THE NW 1/4 OF THE NW 1/4 OF
SECTION 30, T 2 N, R 10 E, W.M.
HOOD RIVER COUNTY, OREGON

2N 10E 30 TAX LOT 400

AUGUST 27,2007, MONUMENTATION DATE



BASIS OF BEARING
BEARINGS BASED ON CS-80082
THE WEST LINE OF SECTION 30



NARRATIVE

THE PURPOSE OF THIS SURVEY WAS TO LOCATE THE SOUTH AND WEST LINES OF THE NORTH HALF OF THE SOUTH HALF OF THE NORTHWEST QUARTER OF THE NORTHWEST QUARTER OF SECTION 30. THIS SURVEY IS BASED ON PREVIOUS SURVEY CS-80082. THE NORTHWEST SECTION CORNER AND THE SOUTHWEST SECTION CORNER WERE HELD AS BASIS OF BEARING AND SECTION SUBDIVISION. GPS CONTROL POINTS WERE ESTABLISHED NEAR THE NORTHWEST SECTION CORNER, THE SOUTHWEST SECTION CORNER AND THE NORTHEAST CORNER OF SAID NORTH HALF. THE CENTER NORTH 1/16 CORNER WAS OCCUPIED WITH GPS RECEIVER. THE WEST 1/16 CORNER AND THE NORTHWEST 1/16 CORNER WERE TIED BY CLOSED TRAVERSE FROM THE GPS CONTROL. A TRAVERSE WAS RUN FROM GPS CONTROL ALONG THE SOUTH LINE OF SAID NORTH HALF AND CLOSED ON GPS CONTROL NEAR THE NORTHWEST SECTION CORNER. THIS SURVEY IS NOT BASED ON CORNERS HELD BY CS-2006-064. WHILE BOTH SURVEYS REPORT BASIS AS CS-80082 WE DO NOT AGREE ON CORNER POSITON. THE WEST 1/16 CORNER ESTABLISHED BY CS-80082 WAS DISTURBED AND NOT USABLE.

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME AT THE REQUEST OF LONGVIEW TIMBER CORPORATION IN JULY 2007.

GEORGE J. FORD, PLS CERTIFICATE NO. 2210

LONGVIEW TIMBER CORPORATION PO BOX 667 LONGVIEW, WASHINGTON 98632 (360) 575—5108 REGISTERED
PROFESSIONAL
LAND SURVEYOR

O R E G O N
JULY 17, 1986
GEORGE J. FORD
2210

EXPIRATION DATE: 12/31/09

RECEIVED DEC 1 0 700 0900 DRAWN BY GEORGE FORD

Sund 1.5