

SECTION OR SUBDIVISION

6/5
2/8

CORNER No. 323

TWP. 7 N., RANGE 10 E., W.M.

CORNER DESCRIPTION

FD. 2" T.P. W/ BRASS CAP

B.T.S:

16" FIR S20°E 1' DIST.

12" FIR S70°W 27' DIST.

16" FIR N77°W, 7' DIST.

14" FIR N49°E, 4.5' DIST.

FROM GORDAN H. RD.

N7°W, 49.5' DIST. (TAG ON

RD.)

W.O. REF. REVISED BY H.R. Co.

CELA 1/1/78

CARD 4 OF 4



LAND CORNER RECORD

5680-2

1. T 2N R 10E No. 7 Cor. NE Mer. W State Oregon (Rectangular) N. F. _____ Dist. _____

2. Corner Status


6x 5
8

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: NE COR Sec 7 1/2" IP 1' above ground
Square tag on tree

5. Investigation Notes: BT Fir snag N 70° E 55 lks readable
BT live 10" Fir S 15° E 40 lks
others gone

7. Photo Identification HR 67
Photo No. L7 Ph 9
Ident. By: _____



8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____


6. Signed A Hutson Title _____ Date 9-29-67

RECOVERY NOTES

PROPERTY CORNER INVESTIGATION

CC0323

LOCATION



T. 2N R. 10E
 Mer. _____ State Oreg.
 Forest Mt Hood Dist. HR.

LEGEND

- Corner searched-no evidence
 ⊗ Corner or accessory found
 ● Corner marked by perm. mon.

DESCRIPTION OF FOUND CORNER

MATERIAL: Pipe SIZE: 1/2"
 HEIGHT ABOVE GROUND: 1' CONDITION: good
 MARKINGS: Square tag on tree

DESCRIPTION OF FOUND ACCESSORIES

1. B.T. fir snag.
 N. 70° E 55 lks
 Readable.
 2. B.T. Live 10" fir
 S 15° E 40 lks -
 others gone -

NOTE: Indicate full investigative details on back of form.

PHOTO IDENTIFICATION

Symbol & date HR67-7-9 Line or Roll _____ Exposure _____
 How Identified Field Where filed _____

RECOVERED BY: _____

DATE: 9/27/67

TITLE: _____