

SECTION OR SUBDIVISION

24	19
25	30

CORNER No.

12

TWP. 2N....., RANGE 9E 10... E, W.M.

CORNER DESCRIPTION

3" BRONZE CAP IN 1/2" I.P.4" X 4" X 72" CEDARPOST SET 1.5' N.E.OF CORNERRESTORED 1972OREGON STATEFORESTRY DEPT.

{ 24" FIR } ORIGINAL
 { DEAD } B.T.



W.O. REF. _____

CARD.....

1

OF

2


SECTION OR SUBDIVISION 24

29	19
25	30

CORNER No. 12

TWP. 2 N., RANGE 9 E, W.M.

CORNER DESCRIPTION



SE Cor. 3" X 3" X 4'

Squarred stake - No markings

one tree bearing S 60° E nothing

No visible scribe

Found 10-1-67 A. Hutson

Flight HR67-6-6

Tag on 2 1/2" D. fir 21' NW
of corLine mark on tree
along Hachett Rd 21' N
from corW.O. REF. cor. is 25' off rd.
in clearing

CARD OF

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 19, 30, 24 and 25, T2N, R9 and 10E, W.M., Hood River County, Oregon.

ORIGINAL

Post (missing, 3/4" iron pipe in place) from which a:

- 10" Fir bears N31E 30 lks.; now 24", down, exposed scribes T2N R10E S19 on slab on underside.
- 10" Fir bears N52W 20 lks.; now 24" dead, exposed scribes T2N R10E S24 BT.
- 36" Fir bears S75E 53 lks.; down and rotted.
- 4" Maple bears S30W 52 lks.; missing, in road.

RESTORED


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R9E R10E S19 S30 S24 S25 1972 RS 359", 34 inches in ground, over above 3/4" iron pipe and from which a:

- 12" Chinquapin bears N48E 55.7 ft. to face; scribed T2N R10E S19 BT.
- 8" White Fir bears S23E 28.7 ft. to face; scribed T2N R10E S30 BT RS 359.
- 5" White Fir bears S82W 64.4 ft. to face; scribed T2N R9E S25 BT.

Set 4"x4"x72" white painted Cedar post 1.5 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on orig. Fir BT N52W.

Dated June 1, 1972

Restored by



Present and witnessed by Frank Blizard
Pete Authier