

1201

OREGON CORNER RESTORATION FORM

Section 6 Township 1 N Range 9 E

County Hood River Date September 13, 2013

CORNER DESIGNATION

South 1/4 Corner Section 6, T1N, R9E

North 1/4 Corner Section 7, T1N, R9E

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals/Surveys, etc. Corner was established by Newton Clark by GLO survey, contract no. 502, dated 1884. Hood River County survey CS-1242, dated 1971, noted no original evidence found. Terra Surveying in survey CS-95105, recorded November 7, 1995, calculated the corner at proportion position.

Monument(s) & Accessories Found: (Condition and Source)

N/A

Monument Detail

Sketch



Monument Set (procedures and Description)

Set 3/4" x 24" Iron Rod with 2" Aluminum cap at proportion position between the found southeast corner and the found southwest corner of section 6

New Accessories

Referenced 14" D. Fir N60°E at 19.45' scribed [1/4 S6 BT]; 7" D. Fir S65°E at 22.2' scribed [1/4 S7 BT]; 12" D. Fir West at 15.5' scribed [1/4 S6 BT]; steel fence post north at 1.0'

Location & Comments  
No comments

Compass Declination 16°E  
Firm/Agency:

Ford Land Surveying  
PO Box 353  
Klickitat, WA 98628  
Party Chief: George Ford  
Notes: Field Book - 2013-4  
Witness: Beverly Ford

Surveyor's Seal

