

March 20, 1972

Field Notes:

A survey for Mr. Ralph Claflin of his property located in the NW 1/4 of the NW 1/4 of Section 33, Township 3 North, Range 10 East, W.M. Hood River County, Oregon.

Crew: R. A. King, L. S.
W. C. Brown, Party Chief
Ed Graham, Chainman

Date completed: March 20, 1972

In November 1971, Mr. Ralph Claflin requested a survey for the purpose of establishing the boundaries of his property.

Information pertaining to corners in this area was located in the office of the Hood River County Surveyor.

The field work involved running a traverse from the center east 1/16th corner to a found iron pipe, reference Dielschneider survey # 71272, an iron rod was set on line at deed distance between this pipe and one found on the east line of lot 23 Town Of Belmont. Iron rods were set at the points at which the east and west property lines intersected the south right of way line of Post Canyon Road.

Monuments found in the course of this survey, 1/4 corner common to Sections 33 & 34, the center east 1/16 th Sec. 33, the SE 1/16th Sec. 33, property corners as shown.

Monuments set in the course of this survey, property corners as shown.

Monuments found and set are shown on the attached drawing, which by reference is made a part of this survey.

W.C. Brown
W. C. Brown

FILED

APR 18 1972

Carl Van Elsberg
COUNTY SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Richard A. King

OREGON
JAN. 1, 1945
RICHARD A. KING
98