

Engineering  
Surveying  
Data Processing


RECEIVED  
DATE 11/16/72

CS 7257

**Dielschneider  
Associates Inc**

No. 8 Fourth St. Hood River, Oregon 97031

Phones: Hood River 503/386-2912, The Dalles 503/296-3721



November 16, 1972

**FIELD NOTES:**

**FOR:** W. B. Van Fleet, in Government Lot 5 of the NW  $\frac{1}{4}$  section  
22, TIN, R10E, WM, Project 72246

**CREW:** A. Klein - Party Chief  
J. Robinson - Instrument man  
M. McClain - Chainman

**DATE COMPLETED:** September 25, 1972

Mr. Van Fleet requested our firm to locate the property as described in the description furnished by him, and set the corners. Also, he requests that additional corners be set on line.

In order to perform the survey, it was required to locate the west line of Section 22. An oak post was found at the NW corner of the section and agreed with notes found at the county surveyors office. Also found a stone with a chiseled X at the N  $\frac{1}{16}$  corner and an iron pipe at the NS  $\frac{1}{64}$  corner. No G.L.O. bearing trees were found at any of these corners, but the  $\frac{1}{64}$  corner and the section corner had bearing trees that were established at some later time, maybe 15 or 20 years ago.

The west  $\frac{1}{4}$  corner was not found but an old stump, that according to notes found at the county surveyors office, which indicated it to be an original bearing tree was found and a dimension from the  $\frac{1}{64}$  corner to the  $\frac{1}{4}$  corner, was found in the same notes. This appears to be the best information available for re-locating the west  $\frac{1}{4}$  corner. A nail was set at the  $\frac{1}{4}$  corner temporarily until the county has an opportunity to set the monument box.

A traverse was run to the SW section corner of the section and a railroad spike found but there was no evidence to support it as being a section corner.

# 7257

**FILED**

NOV 16 1972

*Carl Van Esberg*  
COUNTY SURVEYOR

By

DEPUTY

A fence corner at the NE corner of Government Lot 5 was found and has been previously accepted as the true corner by past surveys and adjoining owners testimony.

All corners found and set during the course of this survey, along with the established bearing and distances are shown on the attached map, which reference is made a part hereof.

Signed

A handwritten signature in cursive script, appearing to read "Anthony C. Klein", written over a horizontal line.

Anthony C. Klein  
Registered Professional Land Surveyor  
No. 932