

CONSULTING
Engineers TENNESON ENGINEERING CORPORATION

April 2, 1982
 W.O. #6161

PHONE (503) 296-9177
 409 LINCOLN STREET
 THE DALLES, ORE. 97058

FIELD NOTES: A survey for ANDY ABRAMS of a tract of land in Section 19,
 Township 1 South, Range 10 East, W.M., Hood River County, Oregon.

CREW: David L. Tuttle, Partychief.
 Lawrence E. Jones, Assistant.

REFERENCES: Survey of Hood River County Forest Lands by H.R. County Surveyor's
 Office, #7574, 1975.
 H. R. County Surveyor's Corner Reference Files.

On March 9, 1981 our firm was retained by Andy Abrams of Parkdale, Oregon to
 survey a tract of land in Section 19, T. 1 S., R. 10 E., W.M. The intent of
 the survey was to run the west line of the north one-quarter, and the east-west
 centerline of the northwest one-quarter. Hood River County Surveyor's office
 provided a copy of their survey #7574 done in 1975 when this section was partially
 subdivided.

The survey was started by running a traverse line from the northwest corner of
 Section 19 to the west one-quarter corner thereof. The northwest corner is a
 Hood River County brass cap monument. A 12" scribed fir bears N. 60° E., 17.9 feet.
 A 12" fir bears S. 55° E., 19.4 feet. The west one-quarter corner is a 3/4" iron
 pipe recovered by Hood River County Surveyor in 1970.

A true line was calculated between these two found corners and the north one-sixteenth
 corner established. A 1/2" iron pipe was set in the center of an 8 foot dirt road.
 A found 3/4" iron pipe bears S. 20° E., 11.7 feet. A true line was run northerly
 from this corner and stakes set for fencing purposes. From the north one-sixteenth
 corner a traverse line was run easterly along the south line of Government Lot No. 1.
 Bearings and distances are based on those appearing and calculated from Hood River
 County Surveyor's drawing #7574, 1975. At 652.11 feet a 1/2" iron rebar was set
 at the northeast corner of the west 20 acres of Government Lot 2. The line was
 continued to the north-south centerline of section and a 5/8" iron rebar set. An
 old fence corner bears South 52° West 22.4 feet. Offsets to true line for logging
 purposes are shown on the attached drawing.

Bearings for this survey are based on the west line of the section as shown on
 County Surveyor drawing No. 7574, 1975. These bearings are based on a solar
 observation. Corners found or set along with measured bearings, distances and ties
 are shown on the attached drawing T.E.C. work order #6161, which by reference is
 made a part hereof.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

CHECKED AND APPROVED:
 Tenneson Engineering Corporation

Donald J. Branton
 DONALD J. BRANTON, President

Signed

David L. Tuttle
 David L. Tuttle, Oregon Surveyor #872

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

OREGON
 DAVID L. TUTTLE
 JULY 12, 1968
 872