



SET BRASS CAP MKD 1/4"
(SET MID. OF STONES.)

22" CEDAR BT.
(FROM 1940 RE-SURVEY G.L.O.)

B.T. 16" HEMLOCK
(FROM 1940 RE-SURVEY)
(G.L.O.)

Corner reset and bearings found as shown.

REGISTERED
OREGON
LAND SURVEYOR

David L. Tuttle

JULY 12, 1968
DAVID L. TUTTLE
872

F I L E D

JAN 13 1969

Clyde Newberry
COUNTY SURVEYOR

DEPUTY

02992

5-6(2)

Date	No.	Revisions		By	App.
Design					
Survey		Scale			
Drawn		Date			
App'd.		Sheet			
		of			
		Wk. Or. No.			

Map Showing Reestablishment of
West 1/4 Corner of Sec. 10,
T 1 S, R 9 E, Hood River County,
Oregon