


T. 1 S see cor. card. # 185  
 25 30  
 R. 9 E 36  
 R. 10 E 31

U.S.F.S. Boundary  
 markers "54-2a"  
 set on line  
 approx. every 5 chains



Basis of Bearing:  $N 01^{\circ} 09' 14'' E$   
 H.R.C. Survey # 7596  
 2636.69'

Resume!

G.L.D. brass caps were found & accepted at the NW corner of sec. 31 and at the W 1/4 corner of sec. 31. A random traverse was run between said corners and was found to agree with H.R.C. survey # 7596 within 0.2'. U.S.F.S. signs # "54-2a" were set on the true line approx. every 5 chains. The survey was completed in Sept. 1979.

Dick Arnold,  
 Party Chief

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

*Anthony C. Klein*

OREGON  
 JULY 19, 1970  
 ANTHONY C. KLEIN  
 932

FILED

JUN 23 1980

*Anthony C. Klein*  
 COUNTY SURVEYOR

DEPUTY

HOOD RIVER COUNTY DEPT. OF PUBLIC WORKS	
" U.S.F.S. Coop Survey "	
Sec. 31 T. 1 S R. 10 E	
Sec. 36 T. 1 S R. 9 E	
DATE: June 1980	DESIGN BY: RJA
SCALE: 1" = 300'	CHECKED BY: RJA
SHEET 1 OF 1	DRAWN BY: RJA

36 31  
 1/4 cor.  
 see cor. card  
 # 355