

Point in bottom of old rock pit site near broken off 40" Doug fir tree broke off ~20-25' above ground
ELEV = 100.0


N. 1/4 COR. SEC. 1
Found - Railroad spike
ELEV. = 152.3

1/2" Iron rod as per D.L.C. 3/12/81 SURVEY
ELEV. = 204.4

1/2" Iron rod as per D.L.C. 3/12/81 SURVEY
ELEV. = 218.7

Invert of overflow pipe at Klindt Spring
Invert ELEV = 218.2

REGISTERED PROFESSIONAL LAND SURVEYOR
Danny L. Cron
OREGON
AUGUST 22, 1975
DANNY L. CRON
1028
April 20, 1981



SCALE = 1" = 300'

Basis of bearing as per D.L.C. 3/12/81 SURVEY

NOTE - elevations are strictly on an assumed datum for the purpose of showing elevation differences.

or SURVEY
FOR Paul Klindt
LOCATION - Elevation differences in Section 1, T.15, R.9E, W.M.
HOOD RIVER COUNTY, OREGON

FILED

JUL 29 1981
Danny L. Cron
COUNTY SURVEYOR
DEPUTY