

T.L. 600 - 3 N 10 36 A
SEE D.L.C. 3/20/85 SURVEY

25 30 SEC. COR.
36 31 Found - Brass Cap

T.L. 1801-3N 11 31 B
SEE D.L.C. 5/13/78 SURVEY

T.L. 1701-3 N 11 31 B
SEE D.L.C. 7/18/78 SURVEY

THE North line of the S 1/2 of the S.W. 1/4 of the N.W. 1/4 of SEC. 31

861.46±

T.L. 2500-3N 11 31 B

SEE D.L.C. 5/16/78 SURVEY

200

435.6

1

B

L

E

C

S

N

PARCEL INFORMATION:

Zoned at R.R. or min. lot size is 1/25±

Parcels are in the Col. Gorge Combining Zone

Approx. 1/3 of T.L. 2401 is in the Geological Hazard Area

PARCEL #2

ASSESSOR
11.12± ACRES = 11.42 + 1.91 - 221

F I L E D

MAR 20, 1987

Richard J. Arnold
TAXIATOR

SEE D.L.C. 12/15/85 SURVEY
HIGHLINE DRIVE

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Danny L. Cron

OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

Mar. 16, 1987


18 SURVEY

FOR - John & Ruth Hukari
LOCATION - Parcels & lot line
adjustment located in SEC. 31,
T. 3 N., R. 11 E., W.M.

HOOD RIVER COUNTY,
OREGON

DLC SURVEYING
DAN CRON 352-8574
5694 TROUT CREEK ROAD
PARKDALE OREGON 97041

87012



scale - 1" = 100'

Basis of Bearing & Survey
Control as per D.L.C. 5/16/78
Survey