



NW COR. of LOT 1  
Position as per D.L.C. 1/25/78

NE COR. of LOT 1  
Position as per D.L.C. 1/25/78

SET 1/2" IR.  
Found 3/8" IR.  
at 1/2 North &  
2.1' West

LOT 4  
EAST BELMONT

LOT 4  
EAST BELMONT  
66.29  
S. 11° 43' 50" W.

Apparent Possession  
Line by usage  
loose rock work &  
shrubbery line with  
existing access road  
on the East side

SW COR. of  
LOT 4

692.80  
690 plat

C.S. 1/16<sup>th</sup> COR.  
Found - Rock nail

original R/W of  
FAIRVIEW ROAD  
Comm. Journal A,  
Pg. 125 being 20'  
on each side

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Danny L. Cron*

OREGON  
AUGUST 22, 1975  
DANNY L. CRON  
1028

FEB. 6, 1988

REVISED 6/4/88  
to show triangular  
shaped piece - D.C.

SCALE - 1"=100'

Basis of Bearing & Survey  
Control as per D.L.C. 1/25/78  
Survey -

NOTE: Iron rod (I.R.) monuments  
set have yellow, plastic cap  
stamped "LS 1028" affixed

NARRATIVE: The purpose of this  
survey was to locate deed  
microfilm No. 783620 by survey -

SE 1/16<sup>th</sup> COR.  
Position as per  
T.I.E.C. - M.O. #4030  
ALSO S.E. cor.  
of LOT 4 of  
EAST BELMONT

S. 1/16<sup>th</sup> S34435  
Found - Brass Cap  
in Men. Case

"SURVEY"

FOR - Larry Blakely  
LOCATION - Parcel located in  
the W 1/2 of the E 1/2 of  
Lots 1 & 4 of platted East  
Belmont being T.L. 901 of  
3N 1034D -

HOOD RIVER COUNTY,  
OREGON

DLC SURVEYING  
DAN CRON 352-6574  
5694 TROUT CREEK ROAD  
PARKDALE, OREGON 97041

**FILED**

MAR 4 1988

*Richard J. And*  
COUNTY SURVEYOR

DEPUTY

88009