



1/4 COR
Found - Brass Cap
Position as per D.L.C. 6/2/84

1/4 COR
Found - Brass Cap

SEC. COR
Position as per
D.L.C. 6/2/84

1/4 COR
Found - Brass Cap

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Danny L. Cron

OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

SCALE - 1" = 200'

Basis of Bearing and Town of Belmont
Survey Control as per D.L.C. 6/2/84 Survey

NOTE: Iron rod (I.R.) monuments set have yellow
plastic cap stamped 75/1028 affixed

NARRATIVE: THE PURPOSE OF THIS SURVEY WAS TO LOCATE
BOUNDARIES AS PER HRC, PARTITION # 88-361 OR T.L. 203
OF 3N 1034C. FENCES WERE FOUND AROUND THE PERIMETER
OF SAID T.L. 203 AND ONE WOULD BE WELL ADVISED TO
SEEK PROPER LEGAL COUNCIL PRIOR TO ATTEMPTING TO
RELOCATE SAID FENCES

"SURVEY"

FOR - Ross Brown
LOCATION - Parcels located in
Lot 2 and the East 40' of vacated
Hall Avenue of platted Town of
Belmont as located in the S.W. 1/4
of Sec. 34, T. 3N, R. 10E, W.M. -
ORIGINAL PARCEL WAS T.L. 203 OF
3N 1034C -

HOOD RIVER COUNTY,
OREGON

DLC SURVEYING
DAN CRON 352-6574
5694 TROUT CREEK ROAD
PARKDALE, OREGON 97041

FILED

DEC 22 1988

Richard A. Jundt
COUNTY SURVEYOR