

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Danny L. Cron

OREGON
AUGUST 22, 1975
DANNY L. CRON
1028

Sept. 19, 1988

SCALE-1"=50'

Basis of Bearing & Survey Control as per plat of James Addition-

NOTE: Iron rod (I.R.) monuments set have yellow, plastic cap stamped "LS 1028" affixed-

NARRATIVE: The Purpose of this survey was to reset the S.E. corner of Lot 11. In the course of the survey it was found that the N.W. corner of Lot 11 had problems as shown. All monuments found, except N.W. of Lot 11, were within 0.15 feet of True Position. In addition to the monuments shown, six monuments were tied on the North end of James Add. to arrive at a plat basis of bearing.

"SURVEY"

FOR- Glenn Adams

LOCATION- Lot 11 of platted James Addition as located in the S.E.1/4 of the S.W. 1/4 of Sec. 35, T.3N., R.10E., W.M.-

HOOD RIVER COUNTY, OREGON

T.L. 818, 3N 10 35CD

DLC SURVEYING
DAN CRON 352-6574
5894 TROUT CREEK ROAD
PARKDALE, OREGON 97041

FILED

DEC 22 1988

Richard G. Gradel
COUNTY SURVEYOR

DEPUTY

#88074