

1/16TH CORNER

The NW corner of the NE 1/4 of the SE 1/4 of Section 36 Found HRC 8/3/70 Brass Cap at N.89°25'25"W, at 1316.85'

285.00' Deed/Held

T.L. 360+ 1400

1321.86' S 89°29'09" E

T.L. 3700- 1300

1/4 CORNER Found HRC Brass Cap 36-31

1322.45' S 00°19'20" W

Parallel Deed/Held

S 00°19'20" W 229.23' 249.23'

Set 1/2" IR

Deed/Held Centerline of East Fork Irrigation Ditch



1/16TH CORNER The SW corner of the NE 1/4 of the SE 1/4 of Section 36

Basis of bearing and survey control as per D.L.C. C.S. 93040.

NOTE: Iron rod (IR) monuments set have yellow, plastic cap stamped "LS 1028" affixed.

NARRATIVE: The purpose of this survey was to locate the West line of existing T.L. 3700 of 2N 10 36D as shown.

### "SURVEY"

FOR — Leo and Rhonda Wilson

LOCATION — Parcel located in the Northeast 1/4 of the Southeast 1/4 of Section 36, Township 2 North, Range 10 East, Willamette Meridian — HOOD RIVER COUNTY, OREGON

June 12, 1996



**FIELD**  
JUN 27, 1995  
Rick G. Hill  
CLAYTON COUNTY SURVEYOR  
DEPUTY

REGISTERED PROFESSIONAL LAND SURVEYOR

Danny L. Cron

OREGON  
AUGUST 22, 1975  
DANNY L. CRON  
1028

DLC SURVEYING  
ESTABLISHED 1976



Dan Cron  
5694 Trout Creek Road  
Parkdale, Oregon 97041  
(503) 352-6574

JUN 12, 1995

SCALE  
1" = 100'

WILS0595.dwg  
WILS0595.cdf  
#95051