
## SURVEY IN SE 1/4. SE 1/4, SEC 34, T 3 N, R 10 E, WM COUNTY OF HOOD RIVER, STATE OF OREGON

3N 10 34D TAX LOT 2800 & 3500



BASIS OF BEARING
KLEIN & ASSOC. CS #2000-104

REFERENCE SURVEYS
SURVEY BY DLC SURVEYING
CS#87071
SURVEY BY DAI SURVEYING
CS#7243
SURVEY BY NEWTON SURVEYING
CS#7233
SURVEY BY KLEIN & ASSOC.

CS #92037, 2000-104

## LEGEND

- SET 5/8" IR WITH PLASTIC CAP MARKED OR #932 & WA #22098 EXCEPT AS NOTED
- O = FOUND MONUMENT AS NOTED
- $\square$  = CALCULATED CORNER AS NOTED

NARRATIVE OF SURVEY
THE PURPOSE OF THIS SURVEY IS TO RESET THE SOUTHEAST CORNER OF
TAX LOT 2800. SAID MONUMENT WAS DISTURBED DURING
CONSTRUCTION OF A NEW IRRIGATION MAIN WATER LINE. PREVIOUS
SET MONUMENTS BY OUR FIRM CS #2000-104 WERE RECOVERED DURING
THIS SURVEY AND SHOWN ON THE FACE OF THIS SURVEY. ALL OTHER
MONUMENTS SHOWN AS FOUND WERE TIED FROM A PERVIOUS SURVEY
BY OUR FIRM CS #2000-104.

S 1/16 CORNER FD 5/8" IR'S/ALUM CAP, HELD. SET BY NEWTON SURVEY, CS#7233 VISITED 2000 159.92'MEA 159.90' AS PER CS#7243 30' EAST LINE SEC 34 CALC AS PER DAI SURVEY CS#7243 159.90' FD 5/8" IR/ALUM CAP, BENT. SET BY DAI SURVEY, CS#7243 VISITED 2000 NOTE: OVERLAP BETWEEN CALC COR AS PER SURVEY CS#7243 & CS#87071 S 89°39'31" E 173.25' SEE NOTE S 89°39'11" E 173.25' FD 1/2" IR/CAP 0.10' FROM CALC POSITION FD K&A 5/8" IR/CAP CS#87071 HELD CS#2000-104 NOTESET 5/8" IRON ROD 1.00 FEET WEST DUE TO IRRIGATION BOX/VALVE AT PROPERTY CORNER PREVIOUS SET 5/8" IRON ROD SET BY OUR FIRM CS #92037 WAS DISTURBED DURING CONSTRUCTION FD K&A 5/8" IR/CAP CS#2000-104 **PROFESSIONAL** LAND SURVEYOR 173.25 <del>7</del> 33.00, N 89°39'11" W OREGON JULY 17, 1970 ANTHONY C. KLEIN 932 BELMONTN 89°39'28" W 2651.81 EXPIRES 6-30-05 FD. BRASS CAP OF RECORDED IN MONUMENT CASE LAND SURVEYING 1418 13TH STREET Hood River, Oregon 97031 Teli (541)386-3322 DATE SURVEYED: AUG. 2004

SURVEY
FOR
FARMERS IRRIGATION

JOB NO.: 04073