



(1) SET LOT CORNER COMMON TO LOTS 43, 44, 53, 54: FOUND NO EVIDENCE OF THIS CORNER HAVING BEEN SET.

SET 3 1/2" X 30" USDA ALUMINUM MONUMENT WITH A MAGNET INSIDE THE MONUMENT. THE CAP IS STAMPED AS SHOWN.

SET A 6' ORANGE FIBERGLASS POST WITH A USFS 54-9 SIGN ATTACHED, ALONG THE SIDE OF THE MONUMENT. THE CAP IS STAMPED AS SHOWN.

SET REFERENCE MONUMENTS AS FOLLOWS: SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED WEST ON THE LOT LINE 4.00' FROM MONUMENT. SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED SOUTH ON THE LOT LINE 6.00' FROM MONUMENT.

1/4 S14 S13


(8) FOUND WEST QUARTER SECTION CORNER TO 13 & 14 WHICH IS THE LOT CORNER COMMON TO LOTS 25 & 40:

THIS CORNER APPEARS TO HAVE BEEN PERPETUATED BY OREGON LUMBER CO. WHEN FIRST ADDITION TO RIVERSIDE PARK WAS PLATTED IN 1911. THE CORNER HAS SINCE BE MONUMENTED BY HOOD RIVER COUNTY WITH A BRASS CAP SET ABOUT 6'

IN A FENCE CORNER NEAR A RAIL ROAD TIE CORNER POST. NO CORNER MAINTENANCE WAS DONE TO PERPETUATE THIS CORNER. IT IS WELL REFERENCED BY COUNTY RECORDS. THE CORNER WAS USED TO VERIFY THE FOUND CONTROLLING CORNERS DESCRIBED ABOVE BUT WAS NOT USED TO CONTROL THE SURVEY.

HOOD RIVER COUNTY

SURVEYOR'S OFFICE



(2) SET LOT CORNER COMMON TO LOTS 53, 54, 59, 60:

FOUND A 1/2" IRON ROD WITH A "WYEAST LS 29288" STAMPED PLASTIC CAP. ASSUMED THIS WAS A WASHINGTON CAP NUMBER AND THE IRON ROD WAS A PART OF C.S. No. 2002006. THE IRON ROD WAS TURNED UPSIDE DOWN AND THE USDA MONUMENT WAS SET IN THE ROD'S POSITION. WE SET 3 1/2" X 30" USDA ALUMINUM MONUMENT WITH A MAGNET INSIDE THE MONUMENT. THE CAP IS STAMPED AS SHOWN.

SET A 6' ORANGE FIBERGLASS POST WITH A USFS 54-9 SIGN ATTACHED, ALONG THE SIDE OF THE MONUMENT. THE CAP IS STAMPED AS SHOWN.

SET REFERENCE MONUMENTS AS FOLLOWS: SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED WEST ON THE LOT LINE 6.00' FROM MONUMENT. SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED NORTH ON THE LOT LINE 6.00' FROM MONUMENT.



(3) SET LOT CORNER COMMON TO LOTS 54, 55, 58, 59:

FOUND A 1 1/2" AXLE AT THE CALCULATED POSITION. NO RECORD OF THE AXLE'S ORIGIN. WE SET 3 1/2" X 30" USDA ALUMINUM MONUMENT WITH A MAGNET INSIDE THE MONUMENT OVER THE AXLE. THE CAP IS STAMPED AS SHOWN.

SET A 6' ORANGE FIBERGLASS POST WITH A USFS 54-9 SIGN ATTACHED, ALONG THE SIDE OF THE MONUMENT. THE CAP IS STAMPED AS SHOWN.

SET REFERENCE MONUMENTS AS FOLLOWS: SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED EAST ON THE LOT LINE 5.00' FROM MONUMENT. SET A 5/8" IRON ROD WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED NORTH ON THE LOT LINE 6.00' FROM MONUMENT.



(4) SET LOT CORNER COMMON TO LOTS 59 & 60:

FOUND NO EVIDENCE OF THIS CORNER HAVING BEEN SET OTHER THAN THE REFERENCED MAHONEY SURVEY. HIS CORNER WAS PROBABLY REMOVED WHEN THE DITCH WAS REPLACED

SET 3 1/2" X 30" USDA ALUMINUM MONUMENT WITH A MAGNET INSIDE THE MONUMENT. THE CAP IS STAMPED AS SHOWN.

SET A 6' ORANGE FIBERGLASS POST WITH A USFS 54-9 SIGN ATTACHED, ALONG THE SIDE OF THE MONUMENT. THE CAP IS STAMPED AS SHOWN.

SET REFERENCE MONUMENTS AS FOLLOWS: SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED WEST AT RIGHT ANGLES TO THE LOT LINE 6.00' FROM MONUMENT. SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED NORTH ON THE LOT LINE 6.00' FROM MONUMENT.




(5) SET LOT CORNER COMMON TO LOTS 58 & 59:

FOUND NO EVIDENCE OF THIS CORNER HAVING BEEN SET OTHER THAN THE REFERENCED MAHONEY SURVEY. HIS CORNER WAS PROBABLY REMOVED WHEN THE DITCH WAS REPLACED

SET 3 1/2" X 30" USDA ALUMINUM MONUMENT WITH A MAGNET INSIDE THE MONUMENT. THE CAP IS STAMPED AS SHOWN.

SET A 6' ORANGE FIBERGLASS POST WITH A USFS 54-9 SIGN ATTACHED, ALONG THE SIDE OF

THE MONUMENT. THE CAP IS STAMPED AS SHOWN. SET REFERENCE MONUMENTS AS FOLLOWS: SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED EAST AT RIGHT ANGLES TO THE LOT LINE 6.00' FROM MONUMENT. SET A 5/8" IRON RODS WITH RED "TERRA OR-PLS 1815" PLASTIC CAP ATTACHED SOUTH ON THE LOT LINE 6.00' FROM MONUMENT.



(6) FOUND LOT CORNER COMMON TO LOTS 42, 43, 54 & 55: THÍS CORNER APPEARS TO HAVE BEEN SET BY OREGON LUMBER CO. WHEN FIRST ADDITION TO RIVERSIDE PARK WAS PLATTED IN 1911. THE CORNER IS LOCATED ABOUT 11" BELOW THE ASPHALT OF IMAI COUNTY ROAD.

THE APPEARS TO HAVE SOME TYPE OF CENTER MARKER INSIDE THE PIPE. SET REFERENCE MONUMENTS AS FOLLOWS: SET A 3" STEEL SURVEY MARKER WITH A 1" HEAD EAST ON THE LOT LINE 6.00' FROM MONUMENT IN THE ASPHALT. SET A 3" STEEL SURVEY

CENTER 1/4 COR

(7) FOUND CENTER OF SECTION 13 WHICH IS THE LOT CORNER COMMON TO LOTS 21, 29, 37 & 36:

MARKER WITH A 1" HEAD SOUTH ON THE LOT LINE 6.00' FROM MONUMENT IN THE ASPHALT.

THIS CORNER APPEARS TO HAVE BEEN SET BY OREGON LUMBER CO. WHEN FIRST ADDITION TO RIVERSIDE PARK WAS PLATTED IN 1911. THE CORNER HAS SINCE BE MONUMENTED BY HOOD RIVER COUNTY WITH A BRASS CAP SET IN A MONUMENT BOX.

NO CORNER MAINTENANCE WAS DONE TO PERPETUATE THIS CORNER. IT IS WELL REFERENCED BY COUNTY RECORDS. THE CORNER WAS USED TO VERIFY THE FOUND CONTROLLING CORNERS DESCRIBED ABOVE BUT WAS NOT USED TO CONTROL THE SURVEY.

FOUND CENTER-EAST ONE SIXTEENTH CORNER OF SECTION 13 WHICH IS THE LOT CORNER COMMON TO LOTS 30, 31, 34 & 35:

THIS CORNER APPEARS TO HAVE BEEN SET BY OREGON LUMBER CO. WHEN FIRST ADDITION TO RIVERSIDE PARK WAS PLATTED IN 1911. THE CORNER IS A 2" IRON PIPE AS FOUND AT THE NORTHWEST CORNER OF LOT 54 DESCRIBED ABOVE. THE CORNER IS FLUSH WITH THE ASPHALT AT THE INTERSECTION OF CARSON HILL DRIVE & COLLINS ROAD. NO CORNER MAINTENANCE WAS DONE TO PERPETUATE THIS CORNER. THE CORNER WAS USED TO VERIFY THE FOUND CONTROLLING CORNERS DESCRIBED ABOVE BUT WAS NOT USED TO CONTROL THE SURVEY.



(10) FOUND QUARTER CORNER COMMON TO SECTIONS 13 & 24 WHICH IS THE LOT CORNER COMMON TO LOTS 60 & 61: THIS CORNER APPEARS TO HAVE BEEN PERPETUATED BY OREGON LUMBER CO. WHEN FIRST ADDITION TO RIVERSIDE PARK WAS PLATTED IN 1911. THE CORNER HAS SINCE BEEN MONUMENTED WITH A BRASS CAP BY HOOD RIVER COUNTY. IT IS LOCATED ABOUT 6" BELOW THE ROCKED SURFACE OF ALDER COUNTY ROAD.

NO CORNER MAINTENANCE WAS DONE TO PERPETUATE THIS CORNER. IT IS WELL REFERENCED BY COUNTY RECORDS. THE CORNER WAS USED TO VERIFY THE FOUND CONTROLLING CORNERS DESCRIBED ABOVE BUT WAS NOT USED TO CONTROL THE SURVEY.



SET 5/8" BY 30" IRON ROD FOR VARIOUS CORNERS AS NOTED ON THE 2 PLAT MAPS. PLACED A 1 1/4" RED PLASTIC CAP ON THE TOP OF EACH IRON ROD. EACH CAP HAS BEEN IMPRINTED AS SHOWN TO THE LEFT OF THIS NOTE. SET A 6' ORANGE FIBERGLASS POST WITH A LSM-130 SIGN ATTACHED, ALONG THE SIDE OF EACH MONUMENT.

NARRATIVE CONTINUED FROM PAGE 1 of 2:

This Narrative is to comply with article 3151.1 of the referenced contract. The survey was performed for the U.S.D.A. Forest Service and the lands surveyed are a part of the National Forest System Lands. The lands are located on the Mt. Hood National Forest in Section 13 of Township 1 North, Range 9 East, Willamette Meridian, Hood River County, Oregon.

The basis of bearing for the survey was established by GPS (4 Static Global Positioning Receivers) using the HARN Station of Ponder 2, N.A.D. 83 (1991) as the Base Station. The ground coordinates for the survey are based on the State Plane Oregon North Zone 3601, grid bearings with a theta angle 0° 48' 32" and scale factor of .99994199.

The purpose of the survey was to provide a boundary survey of the parcel described in the contract documents, locating or setting the property corners, posting the property lines and preparing and filing a survey map of the work performed in accordance with the contract

The survey procedures began by locating existing, known controlling corners of record using 4 LOCUS SOKKIA Static GPS receivers and a TOPCON ITS-1 total station instrument last inspected by Portland Precision Instrument in January, 2002. Once the basic control was set and the controlling corners were adjusted by the Sokkia Least Squares adjustment program, the ITS-1 was used to run control traverses to seek corners which may have been existing but not of record. All control and search traverses using the ITS-1 were compass adjusted with the found corners included in the adjusted loops. The monumented corners were then set from these closed loops.


Please see page 2 of 2 for the description of all corners set or found during the course of the survey. Please see additional NARRATIVE notes on page 1 of 2 explaining the finer points of the results of the survey.

LOCATION OF SURVEY:

LOT 54 AND A PORTION OF LOT 59, FIRST ADDITION TO HOOD RIVER COUNTY BEING A PORTION OF THE SOUTHWEST QUARTER, SECTION 13, TOWNSHIP 1 NORTH, RANGE 9 EAST, WILLAMETTE MERIDIAN, HOOD RIVER COUNTY, OREGON

I, ROY O. GAYLORD, A PROFESSIONAL LAND SURVEYOR REGISTERED IN THE STATE OF OREGON, HEREBY CERTIFY THAT THIS PLAT AND THE NOTES HEREON ARE A CORRECT REPRESENTATION OF A SURVEY I PERFORMED AT THE REQUEST OF THE U.S.D.A. FOREST SERVICE IN ACCORDANCE WITH THE STATUTES OF THE STATE OF OREGON AND THE ARTICLES OF MY CONTRACT.

ROY. O. GAYLORD PLS 1815 THIS PLAT WAS EXAMINED AND ACCEPTED THIS _____ DAY OF _____ THIS PLAT WAS EXAMINED AND ACCEPTED THIS _____ DAY OF ____ _____ MT. HOOD NATIONAL FOREST SUPERVISOR.



REGISTERED

PROFESSIONAL

TERRA SURVEYING

DATE: OCTOBER, 2001 TO AUGUST, 2002 SCALE: 1" = 200'VPROJECT: 201064

ASSESSORS MAP: 1N-9E-13

Expires: June, 20.1/

P.O. BOX 617 HOOD RIVER, OREGON 97031 PHONE & FAX: (541) 386-4531

PAGE 2 OF 2

terra@gorge.net

for U.S.D.A. FOREST SERVICE CONTRACT NUMBER 53-05K3-1-002

DEE SEED ORCHARD BOUNDARY SURVEY